



Property Solutions INC.
Environmental & Engineering Consulting

121 Whittendale Drive, 2B • Moorestown, New Jersey 08057 • 856-813-3000 • Fax 856-813-1068

PHASE I ENVIRONMENTAL ASSESSMENT

of

Desimone/Oxblow Freemont
2600 South 102nd Street and 10110 - 10180 West Marginal Place
Tukwila, King County, Washington 98168

Prepared for:

Mellon Bank, N.A.
One Mellon Bank Center, Room 970
Pittsburgh, Pennsylvania 15258

Prepared by:

Property Solutions Incorporated
3567 NE Shaver Street
Portland, Oregon 97212


December 15, 2004

Property Solutions Project No. 20042586

SERVING YOUR NEEDS NATIONWIDE FROM OUR OFFICES IN:

PHILA • NY • CHICAGO • LA • DALLAS • PORTLAND • ATLANTA • BALTIMORE

DFT 001626



Property Solutions^{INC}

Environmental & Engineering Consulting

3567 N.E. Shaver Street • Portland, Oregon 97212 • 503-528-1329 • Fax 503-528-1333

PHASE I ENVIRONMENTAL ASSESSMENT

of

Desimone/Oxbow Freemont
2600 South 102nd Street and 10110 - 10180 West Marginal Place
Tukwila, King County, Washington 98168

Prepared for:

Mellon Bank, N.A.
One Mellon Bank Center, Room 970
Pittsburgh, Pennsylvania 15258

Prepared by:

Property Solutions Incorporated
3567 NE Shaver Street
Portland, Oregon 97212

Dated: **DEC 15 2004**

Property Solutions Project No. 20042586

Richard G. Levis
Northwest Regional Manager

Kevin J. Billings, P.E.
Senior Vice President

SERVING YOUR NEEDS NATIONWIDE FROM OUR OFFICES IN:

PHILA • NY • CHICAGO • LA • DALLAS • PORTLAND • ATLANTA

DFT 001627

TABLE OF CONTENTS

SECTION	PAGE
PROJECT SUMMARY	
EXECUTIVE SUMMARY	
1.0 INTRODUCTION.....	1
1.1 PURPOSE	1
1.2 SCOPE OF WORK	1
1.3 SIGNIFICANT ASSUMPTIONS	2
1.4 LIMITATIONS AND EXCEPTIONS OF THE ASSESSMENT.....	3
1.5 SPECIAL TERMS AND CONDITIONS	4
1.6 RELIANCE	4
2.0 GENERAL PROPERTY INFORMATION.....	4
2.1 PROPERTY LOCATION.....	4
2.2 PROPERTY DESCRIPTION	4
2.3 PROPERTY OPERATIONS	5
2.4 UTILITIES	6
3.0 PHYSICAL SETTINGS	6
3.1 TOPOGRAPHY/REGIONAL DRAINAGE	6
3.2 SOILS	7
3.3 UNDERLYING FORMATION	7
3.4 GROUNDWATER	7
4.0 NEIGHBORING PROPERTIES	7
5.0 HISTORICAL PROPERTY INFORMATION.....	8
5.1 CITY DIRECTORIES	8
5.2 AERIAL PHOTOGRAPHS	9
5.3 FIRE INSURANCE MAPS	10
5.4 TOPOGRAPHIC QUADRANGLE MAP	11
5.5 PRIOR USE INTERVIEWS	11
5.6 PREVIOUS REPORTS AND PLANS.....	12
6.0 ENVIRONMENTAL RECORD RESEARCH.....	12
6.1 PROPERTY-SPECIFIC RECORDS.....	12
6.2 ENVIRONMENTAL DATABASE INFORMATION.....	13

20042586

7.0	PROPERTY VISIT	18
7.1	ASTM SCOPE CONSIDERATIONS.....	19
7.1.1	UNDERGROUND STORAGE TANKS.....	19
7.1.2	ABOVEGROUND STORAGE TANKS.....	19
7.1.3	POLYCHLORINATED BIPHENYL-CONTAINING ELECTRICAL EQUIPMENT	19
7.1.4	HYDRAULIC EQUIPMENT	19
7.1.5	CHEMICAL, HAZARDOUS MATERIALS, AND RAW MATERIALS STORAGE AND USAGE.....	20
7.1.6	WASTE GENERATION, STORAGE, AND DISPOSAL	20
7.1.7	WELLS, SUMPS, PITS, AND FLOOR DRAINS.....	20
7.1.8	STORMWATER RUNOFF AND SURFACE WATER	20
7.1.9	LAGOONS, SEPTIC SYSTEMS, AND SEPARATORS.....	21
7.1.10	STRESSED VEGETATION, STAINING, AND ODORS	21
7.1.11	SURFICIAL DISTURBANCE	22
7.1.12	ON-PROPERTY DRY CLEANERS.....	22
7.2	ASTM NON-SCOPE CONSIDERATIONS	22
7.2.1	ASBESTOS-CONTAINING MATERIALS	22
7.2.2	RADON.....	22
7.2.3	LEAD-BASED PAINT	23
7.2.4	LEAD IN DRINKING WATER	23
7.2.5	POTENTIAL WETLANDS	23
7.2.6	AIR EMISSIONS.....	24
7.2.7	MOLD/ WATER INTRUSION.....	24
8.0	CONCLUSIONS AND RECOMMENDATIONS	24
9.0	REFERENCES	25
9.1	INFORMATION SOURCES.....	25
9.2	DEFINITIONS.....	25
9.3	ACRONYMS	27

APPENDICES

APPENDIX A	MAPS
APPENDIX B	PROPERTY PHOTOGRAPHS
APPENDIX C	CITY DIRECTORIES
APPENDIX D	AERIAL PHOTOGRAPHS
APPENDIX E	FIRE INSURANCE MAPS
APPENDIX F	CORRESPONDENCE
APPENDIX G	ENVIRONMENTAL DATABASE
APPENDIX H	PROFESSIONAL QUALIFICATIONS

20042586

PROJECT SUMMARY

Client Name:	Mellon Bank, N.A.	Property Visit Date:	August 18, 2004
Client Contact:	Dolores Selby	Date of Construction:	1987
Property Solutions Project No.:	20042586	No. Bldgs./Units:	4 Bldgs. / 7 Units
Property Solutions Project Manager:	Rick Levis	No. of Stories:	One Story
Phone No.:	(503) 528-1329	Bldg. Square Footage:	Not Available
Email:	rlevis@propertysolutionsinc.com	Property Acreage:	11.68-acres
Property Name:	Desimone/Oxbow Freemont	Basement/ Slab-on-grade:	Slab-on-Grade
Property Address:	2600 South 102nd Street and 10110 - 10180 West Marginal Place	Property Use:	Lt. Industrial
Property Town, County, State:	Tukwila, King County, WA	Property History:	Undeveloped Land
Property Identification:	0423049073 and 0423049001	Other Improvements:	Office Trailers/ Temporary Structures

Our review of general property information, observation of adjacent properties, research of historical property information, including a review of environmental records, and a property visit revealed the following:

	No Further Action	ASTM Non-scope considerations	HREC	REC	Opinion of Probable Cost	Refer to Section
Property Operations	X					2.3
Neighboring Properties	X					4.0
Historical Review	X					5.0
Previous Reports	X					5.6
Regulatory Review	X					6.0
USTs	X					7.1.1
ASTs	X					7.1.2
PCBs	X					7.1.3
Chemicals/Hazardous Materials/Raw Materials		(1)			N/A	7.1.6
Waste Generation/Disposal	X					7.1.7
Stressed Vegetation, Staining, and Odors		(2)			N/A	7.1.10
Surficial Disturbances	X					7.1.11
ACMs	X					7.2.1
Radon	X					7.2.2
Lead-Based Paint	X					7.2.3
Lead in Drinking Water	X					7.2.4

20042274

	No Further Action	ASTM Non-scope considerations	HREC	REC	Opinion of Probable Cost	Refer to Section
Other	X					

Notes / Recommendations: To understand the property and report, you must read the Executive Summary and complete report.

Recognized Environmental Conditions

1. Chemicals stored on the subject property are minimal quantities of domestic cleaning chemicals, maintenance chemicals and paints. An additional four 55-gallon drums containing grease and concrete finishers were observed on the exterior portion of the subject property. These drums are the responsibility of Freemont Associates. No staining or leaking was observed below the drums. Based on observations made during the property visit, the observed chemicals are not expected to be an environmental concern to the subject property at this time.

As a best management practice, Property Solutions recommends that the drums be placed under cover and on a concrete slab to prevent direct exposure to stormwater and surficial soils.

2. No evidence of stressed vegetation, staining, or odors was noted on the subject property during the property visit, with the exception of one surficial stain noted on the Dick's Towing lot. The stain measured approximately 2' x 2', was surficial in nature, and was observed on a gravel floor within a covered storage building.

Based upon the limited extent of the stain, this stain is not expected to have significantly adversely impacted the environmental condition of the subject property. However, as a best management practice, the stained gravel should be removed and disposed of in accordance with applicable regulations.

20042586

EXECUTIVE SUMMARY

Property Solutions Incorporated (Property Solutions) conducted a Phase I Environmental Assessment of the Desimone/Oxbow Freemont property located at 2600 South 102nd Street and 10110 - 10180 West Marginal Place in Tukwila, King County, Washington 98168 (subject property) at the request of Mellon Bank, N.A.

The subject property consists of an irregular-shaped, +/-11.68-acre parcel of land located on the northeast corner of the intersection of West Marginal Place and South 102nd Street. The subject property is improved with four, light-industrial buildings constructed in approximately 1950 (subject buildings). The subject property is also improved with commercial office trailers and other non-permanent sheds and structures. The remaining portions of the subject property are covered with a combination of paved and gravel parking areas. No water bodies are located on the subject property. Vehicular access to the subject property is gained via driveways along the southeast and southwest sides of the subject property.

The subject buildings are steel framed buildings with metal panel siding and are of slab-on-grade construction. Interiors consisted of concrete slab floors and exposed wall and ceiling members. The subject buildings are heated by electricity.

The subject property consisted of undeveloped land prior to the construction of the current improvements with the occasional on-property storage of materials.

We have performed a Phase I Environmental Assessment in conformance with the scope and limitations of ASTM Practice E1527-00 of the Desimone/Oxbow Freemont property located at 2600 South 102nd Street and 10110 - 10180 West Marginal Place, Tukwila, King County, Washington 98168. Any exceptions to, or deletions from, this practice are described in Section 1.0 of this report.

This assessment has revealed no evidence of recognized environmental conditions in connection with the subject property except for the following:

1. Chemicals stored on the subject property are minimal quantities of domestic cleaning chemicals, maintenance chemicals and paints. An additional four 55-gallon drums containing grease and concrete finishers were observed on the exterior portion of the subject property. These drums are the responsibility of Freemont Associates. No staining or leaking was observed below the drums. Based on observations made during the property visit, the observed chemicals are not expected to be an environmental concern to the subject property at this time.

As a best management practice, Property Solutions recommends that the drums be placed under cover and on a concrete slab to prevent direct exposure to stormwater and surficial soils.

20042586

2. No evidence of stressed vegetation, staining, or odors was noted on the subject property during the property visit, with the exception of one surficial stain noted on the Dick's Towing lot. The stain measured approximately 2' x 2', was surficial in nature, and was observed on a gravel floor within a covered storage building.

Based upon the limited extent of the stain, this stain is not expected to have significantly adversely impacted the environmental condition of the subject property. However, as a best management practice, the stained gravel should be removed and disposed of in accordance with applicable regulations.

20042586

1.0 INTRODUCTION

Property Solutions Incorporated (Property Solutions) conducted a Phase I Environmental Assessment of the Desimone/Oxbow Freemont property located at 2600 South 102nd Street and 10110 - 10180 West Marginal Place in Tukwila, King County, Washington 98168 (subject property) at the request of Mellon Bank, N.A. The subject property is identified as Parcel Numbers 0423049073 and 0423049001, according to the King County Tax Assessor.

A property location map is included in Appendix A.

This Phase I Environmental Assessment was conducted in general accordance with industry-accepted practices, Standard and Poor's Plus Protocol, and American Society for Testing and Materials (ASTM) Standard E 1527-00. The work was authorized by the Notice to Proceed dated August 12, 2004.

1.1 Purpose

The purpose of a Phase I Environmental Assessment is to evaluate issues that may have an impact on the subject property. The goal of this process is to identify the presence or likely presence of hazardous substances or petroleum products on the property and identify conditions that indicate an existing release, a past release, or a material threat of a release of hazardous substances or petroleum products into structures on the property or into the ground, groundwater, or surface of the property. The purpose of this report is not intended to include de minimis conditions that generally do not present a material risk of harm to public health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. This report is also not intended to serve as a compliance assessment of the subject property.

1.2 Scope of Work

This Phase I Environmental Assessment was conducted in accordance with the following Scope of Work:

1. Researched and reviewed available information regarding past owners and occupants of the subject property to assess the potential for contamination resulting from prior on-property activities. Aerial photographs, city directories, topographic maps, interviews and fire insurance maps were utilized, as available.
2. Researched available information regarding immediately adjacent properties for evidence of environmental contamination that could adversely impact the subject property.
3. Interviewed available persons familiar with current and former on-property activities for relevant information regarding potential areas of environmental concern.

4. Reviewed federal and state regulatory agency database information for the subject property and neighboring properties to identify potential concerns that could adversely affect the environmental condition of the subject property. The database review included, but was not limited to, a review of the following lists: United States Environmental Protection Agency (USEPA) National Priorities List (NPL) Sites, Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Sites, State Hazardous Waste Sites, Resource Conservation and Recovery Act Information System (RCRIS) Corrective Action, Generator, and Treatment, Storage, and Disposal (TSD) Sites, Leaking Registered Storage Tank (LRST) Sites, Registered Storage Tank (RST) Sites, landfills, and Emergency Response Notification System (ERNS) Sites. Contacted federal, state, and local regulatory agencies.
5. Performed a property visit to identify areas of environmental concern such as the bulk storage of regulated substances, underground/aboveground storage tanks, asbestos-containing materials, electrical transformers, or process-related wastes. To the extent possible, a review of immediately adjacent properties was also performed from the subject property and public thoroughfares.
6. Prepared a technical Phase I Environmental Assessment report to document the findings regarding the current environmental condition of the subject property. If warranted, the report contains recommendations for further action.

1.3 Significant Assumptions

The following assumptions are made by Property Solutions in this report. Property Solutions relied on information derived from secondary sources including government agencies, the client, designated representatives of the client, property contact, property owner, property owner representatives, computer databases, and personal interviews. Except as set forth in this report, Property Solutions has made no independent investigation as to the accuracy and completeness of the information derived from secondary sources including government agencies, the client, designated representatives of the client, property contact, property owner, property owner representatives, computer databases, or personal interviews and has assumed that such information is accurate and complete. Property Solutions assumes information provided by or obtained from governmental agencies including information obtained from government websites is accurate and complete. Groundwater flow and depth to groundwater, unless otherwise specified by on-property well data, are assumed based on contours depicted on the United States Geological Survey topographic maps. Property Solutions assumes the property has been correctly and accurately identified by the client, designated representative of the client, property contact, property owner, and property owner's representatives.

1.4 Limitations and Exceptions of the Assessment

The findings, observations, conclusions, and recommendations of this report are limited by the contract technical requirements and the methods used to perform the services outlined in the scope of work. These services have been performed in accordance with the described scope for Phase I Environmental Assessments. In order to perform a comprehensive environmental evaluation, subsurface investigation and testing would be required to definitively evaluate whether contamination has affected the subject property. Therefore, the findings, conclusions, and recommendations presented herein are based solely on the scope of work previously described and information gathered. Incomplete or outstanding information identified throughout the body of this report is considered a limitation to the assessment. Limitations to the assessment also include weather conditions, vegetation cover, parked cars, trucks, dumpsters, and anything limiting visual observation of the subject property and neighboring properties.

No environmental assessment can wholly eliminate uncertainty regarding the potential for recognized environmental conditions in connection with a property. Performance of this practice is intended to reduce, but not eliminate, uncertainty regarding the potential for recognized environmental conditions in connection with a property, and both practices recognize reasonable limits of time and cost.

Appropriate inquiry does not mean an exhaustive assessment of a clean property. There is a point at which the cost of information obtained or the time required to gather it outweighs the usefulness of the information and, in fact, may be a material detriment to the orderly completion of transactions. One of the purposes of this practice is to identify a balance between the competing goals of limiting the costs and time demands inherent in performing an environmental assessment and the reduction of uncertainty about unknown condition resulting from additional information.

All findings, conclusions, and recommendations stated in this report are based upon facts, circumstances, and industry-accepted procedures for such services as they existed at the time this report was prepared (i.e., federal, state, and local laws, rules, regulations, market conditions, economic conditions, political climate, and other applicable matters.). All findings, conclusions, and recommendations stated in this report are based on the data and information provided, and observations and conditions that existed on the date and time of the property visit. Responses received from local, state, or federal agencies or other secondary sources of information after the issuance of this report may change certain facts, findings, conclusions, or circumstances to the report. A change in any fact, circumstance, or industry-accepted procedure upon which this report was based may adversely affect the findings, conclusions, and recommendations expressed in this report.

This report was prepared for determining whether to make a loan evidenced by a note secured by the property and not for pre-purchase due diligence.

1.5 Special Terms and Conditions

This Phase I Environmental Assessment was prepared in accordance with the stated and agreed upon Scope of Work. No special terms and conditions are applicable to this Phase I Environmental Assessment.

1.6 Reliance

This report has been prepared for the sole benefit of Mellon Bank, N.A., and may not be relied upon by any other person or entity without the written authorization of Property Solutions.

2.0 GENERAL PROPERTY INFORMATION

2.1 Property Location

Property Location	
Property Name	Desimone/Oxbow Freemont
Property Address	2600 South 102nd Street and 10110 - 10180 West Marginal Place
Property Town, County, State	Tukwila, King County, Washington 98168
Property Tax Identification	Parcel Numbers 0423049073 and 0423049001 (King County Tax Assessor)
Property Topographic Quadrangle	<u>Seattle South, Washington</u>
Nearest Intersection	South 102 nd Street/ West Marginal Place
Area Description	Developed industrial area

An excerpt from the USGS 7.5-minute series topographic quadrangle map of Seattle South, Washington, locating the subject property, is included in Appendix A.

2.2 Property Description

Property Information	
Property Acreage	11.68-acres acres (King County Tax Assessor)
Property Shape	Irregular
Property Use	Light-Industrial

Property Information	
Number of Buildings	Four
Number of Stories	One
Date of Construction	Approximately 1987 (Per Interviews and aerial photographs)
Building Square Footage	Not Available
Basement/Slab-on-grade	Slab-on-grade
Number of Units	Seven
Ceiling Finishes	Exposed Structural Members
Floor Finishes	Concrete
Wall Finishes	Metal
HVAC	Electric
Renovation Date	Not Applicable
Renovation Description	Not Applicable
Vehicular Access	South 102 nd Street and West Marginal Place
Other Improvements	Non-permanent sheds, commercial office trailers
Property Coverage	Footprints of the subject buildings and associated paved and gravel parking areas

A property diagram of the subject property is included in Appendix A.

2.3 Property Operations

The subject property is occupied by multiple tenants that utilize the property for various light-industrial and commercial uses including an automobile impound yard, trailer staging area, container repair, and scrap material recycling.

At the time of the property visit, the subject property was occupied by the following tenants:

Tenant	Operations
Pacific Northwest Transfer (2600 South 102 nd Street)	Scrap metal and used parts collector
Eagle Systems (10180 West Marginal Place)	Trailer staging area
Royal Wolfe (10160 West Marginal Place)	Container staging and repair

Tenant	Operations
Certified Cleaning/Pacific Freight	Truck Parking
Dick's Towing (10140 West Marginal Place)	Car Impound Lot
Vacant Lot (10110 West Marginal Place)	Vacant
Freemont Associates	Residual construction equipment storage

No industrial or manufacturing operations were observed at the subject property at the time of the property visit.

No environmental concerns were identified at the subject property based on the operations observed during the property visit.

2.4 Utilities

The following companies and municipality currently provide utility services to the subject property:

Utility	Provider
Electricity	Seattle City Light
Sanitary Sewerage	Val-Vue Sewer District
Potable Water	City of Tukwila
Solid Waste Removal	Private Waste Haulers

3.0 PHYSICAL SETTINGS

3.1 Topography/Regional Drainage

Review of the United States Geological Survey (USGS) 7.5-minute series topographic quadrangle map of Seattle South, Washington reveals that the elevation of the subject property ranges from approximately 10 to 15 feet above mean sea level. Topography in the vicinity of the subject property appears to decline to the north-northeast, toward the Duwamish River. Regional drainage appears to flow toward the east-northeast, toward the Duwamish River, which is located immediately north of the subject property.

A copy of the USGS 7.5-minute series topographic quadrangle map of Seattle South, Washington is included in Appendix A.

3.2 Soils

Based on a review of the United States Department of Agriculture, Soil Conservation Service's Soil Survey of King County, Washington, it was determined that the subject property exists outside the limits of the soil survey.

Based on the industrial and commercial area in which the subject property exists as well as its proximity to the Duwamish River, the soils in the vicinity of the subject property are expected to be classified as Urban land. Eighty-five percent or more of the soils are covered with office buildings, service buildings, hotels and motels, industrial buildings and yards, streets and sidewalks, parking lots, railroads, shopping centers, closely spaced residences, and other works and structures.

3.3 Underlying Formation

According to information contained in the report entitled Special Report, Radon in Washington, the subject property is located in the physiographic province of the Puget Lowlands. The Puget Lowlands are underlain by a glacial till substrate. It covers both uplands and slopes because it accumulated on pre-existing topography. The till is a nonsorted mixture of clay, silt, sand, pebbles, cobbles and boulders in various amounts. Though generally quite sandy, it locally contains much clay. It typically is hard lodgement till, which is largely a result of compaction caused by the great weight of overriding ice, hundreds of meters thick. The till was deposited directly by the ice as it advanced over an eroded, irregular surface of older formations and sediments. Distinctive features of the till are compactness, the vertical slope maintained, a fissility or sheeting near and parallel to the ground surface, and it's heterogeneous, non-sorted internal structure which resembles a concrete mix.

3.4 Groundwater

Based on a review of the USGS topographic quadrangle map of Seattle South, Washington, it is expected that the depth to shallow groundwater is approximately ten to fifteen feet below ground surface (bgs). Local groundwater is expected to mirror local topography and migrate to the north-northeast, toward the Duwamish River.

4.0 NEIGHBORING PROPERTIES

Review of neighboring properties from the subject property and from public thoroughfares, and research of available information regarding the neighboring properties, were performed to identify evidence of environmental concerns that could adversely impact the subject property. The subject property is located in a mixed-use industrial and commercial area of Tukwila, Washington.

Direction	Property	Address	Operations
Northwest	Duwamish River	Not Applicable	Water Body

Direction	Property	Address	Operations
Southeast	South 102 nd Street	Not Applicable	Public Thoroughfare
	United State Postal Service	10600 West Marginal Way	Mail Sorting Facility
	Commercial Building	2811 South 102 nd Street	Commercial Office
Northeast	Parking Lot	Not Applicable	Parking Lot
Southwest	West Marginal Place and Highway 99	Not Applicable	Public Thoroughfare

Based on a review of neighboring properties from the subject property and from public thoroughfares, the neighboring properties do not appear to be of the type likely to pose a significant threat to the environmental condition of the subject property. The neighboring properties were not listed in the environmental database reviewed or Envirofacts, with the exception of the northwest and southeast adjoining properties, which were listed as a National Priorities List (NPL) site and a generator of hazardous waste site respectively.

Based upon a review of the information obtained in the environmental database, the neighboring properties are not expected to have adversely impacted the environmental condition of the subject property. Therefore, no further action is recommended at this time. These properties are further discussed in Section 6.

A property diagram including neighboring properties is included in Appendix A. Photographs including the neighboring properties are included in Appendix B.

5.0 HISTORICAL PROPERTY INFORMATION

5.1 City Directories

Source: Environmental Data Resources of Milford, Connecticut		
City Directory Type: Polk's for the years 1961, 1968, 1973, 1978, 1983, 1988 and 1996		
Year	Address	Listing
1961-1988	2600 South 102nd Street and 10110 - 10180 West Marginal Place	Streets Not Listed
1996	2600 South 102nd Street and 10110 - 10180 West Marginal Place	Constructor's Pacific

SP - Subject property

No evidence of environmental concern on the subject property or adjoining properties was revealed during a review of the city directories.

A copy of the city directories is included in Appendix C.

5.2 Aerial Photographs

Property Solutions obtained aerial photographs of the subject property and surrounding area for the years 1956, 1965, 1977, 1985 and 1990 from EDR. Property Solutions also reviewed aerial photographs for the years 1998 and 2002 on the King County GIS website. The aerial photographs were reviewed for evidence of environmental concerns on or near the subject property. The following is a discussion of the aerial photograph review:

1956: Review of the 1956 aerial photograph revealed that the subject property largely consisted of undeveloped land. A few small structures or vehicles were observed throughout the property.

The adjoining properties to the southwest and southeast were not depicted on the 1956 fire insurance map. The northwest adjoining property consisted of undeveloped land. The northeast adjoining property was improved with the Duwamish River and undeveloped land with materials stored.

1965: Review of the 1965 aerial photograph revealed no major changes to the subject property in comparison to the 1956 aerial photograph with the exception that no structures or vehicles were observed on the subject property.

The northeast adjoining property was improved with a surface parking lot. The northwest adjoining property was improved with the Duwamish River and undeveloped land. The southeast and southwest adjoining properties consisted of undeveloped land.

1977: Review of the 1977 aerial photograph revealed no major changes to the subject property in comparison to the 1965 aerial photograph with the exception that a few small sheds or vehicles were observed on the northwestern portion of the subject property.

1985: Review of the 1985 aerial photograph revealed no major changes to the subject property in comparison to the 1977 aerial photograph with the exception that unpaved roads were observed traversing the subject property. Several small to medium size sheds and one building were observed along the northwestern corner of the subject property.

No major changes to the adjoining properties were observed in comparison to the 1977 aerial photograph, with the exception that a boat appears to be docked immediately adjacent to the subject property and in the Duwamish River.

1990: Review of the 1990 aerial photograph revealed major changes to the subject property in comparison to the 1985 aerial photograph. Specifically, three large sections of material were observed along the southeastern portion of the subject property. This material appears to be trailers associated with a trucking business. Additional structures were observed in the current locations of the subject buildings.

No major changes to the adjoining properties were observed in comparison to the 1985 aerial photograph, with the exception of the southeast adjoining properties, which were improved with commercial buildings.

1998: Review of the 1998 aerial photograph revealed major changes to the subject property in comparison to the 1990 aerial photograph. Specifically, the three large structures observed along the southeastern portion of the subject property were not present in the 1998 aerial photograph. The subject property appeared to exist largely as it was observed during the property visit.

No major changes to the adjoining properties were observed in comparison to the 1990 aerial photograph.

2002: Review of the 2002 aerial photograph revealed no major changes to the subject property or adjoining properties in comparison to the 1998 aerial photograph.

Review of the aerial photographs revealed that the subject buildings appear to have been constructed after 1985 and prior to 1990. The aerial photographs revealed that the subject property largely consisted of undeveloped land with the presence of small sheds and structures present prior to the placement of the current subject buildings.

No evidence of environmental concern on or adjacent to the subject property was revealed during a review of the aerial photographs.

Copies of the aerial photographs are included in Appendix D.

5.3 Fire Insurance Maps

Fire insurance maps that include the subject property were requested from Environmental Data Resources, Inc. (EDR) of Milford, Connecticut. EDR has informed Property Solutions that no historical map coverage is available for the subject property in the EDR historical map collection.

A copy of EDR's statement of no coverage is included in Appendix E.

5.4 Topographic Quadrangle Map

A review of the USGS 7.5-minute series topographic quadrangle map of Seattle South, Washington was performed to identify evidence of man-made structures, fill areas, and natural features that may have an adverse effect on the environmental condition of the subject property. The Seattle South, Washington topographic quadrangle map was issued 1983, based on aerial photographs taken in 1977.

Review of the Seattle South, Washington topographic quadrangle map revealed that the subject buildings are not depicted on the subject property. No structures were depicted on the subject property. The subject property was depicted as an undeveloped parcel of land.

Adjoining properties also consisted of undeveloped land. The Duwamish River was observed northwest of the subject property.

No environmental concerns were identified based upon a review of the Seattle South, Washington topographic quadrangle map.

A portion of the USGS 7.5-minute series topographic quadrangle map of Seattle South, Washington, which includes the subject property, is included in Appendix A.

5.5 Prior Use Interviews

Property Solutions interviewed Mr. Doug Scheuman and Mr. Craig Peterson, representatives of Freemont Associates, regarding the history of the subject property. Mr. Scheuman and Mr. Peterson have been associated with the subject property for approximately 18 years. Mr. Scheuman stated that his company initially occupied the subject property in approximately 1987. Mr. Scheuman added that the property consisted of vacant land with the exception of the presence of some squatters on the northern portion of the subject property. Mr. Scheuman stated that a ferry boat was present in the adjoining Duwamish River at the time they initially occupied the property and that the owner of the ferry was squatting on the property. Mr. Scheuman added that fill material including approximately 1.5 feet of gravel was brought onto the subject property to create the existing gravel parking lot. Mr. Scheuman stated that the subject property previously contained silty material.

Mr. Scheuman added that one tenant identified as Xtra Lease occupied the southern portion of the subject property and utilized the southern portion of the property for the storage of trailers from approximately 1990 through approximately 2001.

No environmental concerns were identified during the interviews with Mr. Scheuman and Mr. Peterson.

5.6 Previous Reports and Plans

Property Solutions did not receive and is not aware of previous environmental reports or plans pertaining to the subject property.

Property Solutions did not review any plans pertaining to the subject property.

6.0 ENVIRONMENTAL RECORD RESEARCH

6.1 Property-Specific Records

During the course of the assessment of the subject property, Property Solutions contacted the following local, county, and state agencies via phone, letter, or in person.

- King County Tax Assessor
Seattle, Washington

The subject property is identified as Parcel Numbers 0423049073 and 0423049001, according to the King County Tax Assessor.

- Washington State Department of Ecology
Bellevue, Washington

A review of available Ecology databases did not reveal a listing for the subject property's addresses with the exception of Xtra Lease Seattle Branch, which was listed as a Hazardous Waste Generator. Property Solutions obtained additional information from Mr. Kathleen Kaynor of Ecology regarding the current status listing of this site. According to Ms. Kaynor, this facility declared themselves as a RCRA Small Quantity Generator site from at least 1995 through 2000. Ms. Kaynor added that no wastes were reported as being generated in 2001 and that the listing was withdrawn at the end of 2001. Based on the above information, no further action regarding this listing is recommended at this time.

At the time this report was prepared, the following local agencies had not responded to our information request.

- Tukwila Building Department
Tukwila, Washington
- Tukwila Fire Department
Tukwila, Washington
- Val-View Sewer District
Seattle, Washington

- King County Wastewater Program-Eastgate Public Health Center
Bellevue, Washington

According to ASTM E 1527-00, Section 7.1.4.2, information that has been requested must be reasonably ascertainable as part of performing the Phase I Environmental Assessment. Information that is reasonably ascertainable per ASTM means that information will be provided by the source within 20 calendar days of receiving a written, telephone, or in-person request. Copies of the letters and records of communication are included in Appendix F.

Property Solutions contacted the United States Environmental Protection Agency (USEPA) through an on-line search via the Internet to obtain information concerning the subject property. Property Solutions performed a search of Envirofacts, a USEPA-generated website that integrates data extracted from five major USEPA program systems: Aerometric Information Retrieval System (AIRS)/AIRS Facility Subsystem (AFS), Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS), Permit Compliance System (PCS), Resource Conservation and Recovery Information System (RCRIS) and Toxic Chemical Release Inventory System (TRIS), using two integrating databases: Facility Index System (FINDS) and Envirofacts Master Chemical Integrator (EMCI).

Property Solutions generated a printout of all facilities under the programs identified above that are located within the subject property's zip code (98168). A former tenant of the subject property located at 10180 West Marginal Place South (Xtra Lease Seattle Branch) was listed as a generator of hazardous waste. The query was executed on August 17, 2004. Additional information regarding this listing is included in Section 6.2.

A copy of the search results is included in Appendix E.

6.2 Environmental Database Information

As part of the Phase I Environmental Assessment, Property Solutions utilized Environmental Data Resources, Inc. (EDR) of Southport, Connecticut, as an information source for regulatory agency environmental database records. The environmental database was dated August 23, 2004.

Data supplied by EDR is included in Appendix F.

The following summary of the database information is divided into two parts. The first part lists sites as identified and located by EDR within the specified radii of the subject property. The second part contains a discussion of orphan sites, which could not be radius-located by EDR due to incomplete and/or inaccurate address information included in the United States Environmental Protection Agency (USEPA)/state databases.

Although the exact locations of the orphan sites are frequently unknown, Property Solutions attempts to evaluate the potential adverse environmental impact that these sites may have on the subject property. This evaluation consists of reviewing street names in an effort to learn whether the street

on which the site is located lies within the radius of the subject property, a drive-by view of surrounding properties during the site visit, and evaluating the site type and information provided by government agencies. The orphan sites included in the following table are those Property Solutions expects to be located within the identified radius. A complete listing of sites is included in Appendix F.

Environmental Database Summary

Database	Radius	Plottable	Orphan
National Priorities List	1 Mile	1	0
State Hazardous Waste Sites	1 Mile	13	0
RCRA Corrective Action Treatment/ Storage/ Disposal (TSD) Facilities (CORRACTS)	1 Mile	2	0
CERCLIS Sites	½ Mile	1	0
CERCLIS No Further Remedial Action Planned (NFRAP) Sites	½ Mile	1	0
RCRA Non-Corrective Action TSD Facilities	½ Mile	0	0
Leaking Registered Storage Tank Sites	½ Mile	6	0
Solid Waste Landfill Sites	½ Mile	0	0
Washington Voluntary Cleanup Program Sites/ Independent Cleanup Report Sites	½ Mile	7	0
RCRA Large Quantity Generators	Subject Property and Adjoining Properties	0	0
RCRA Small Quantity Generators	Subject Property and Adjoining Properties	2*	0
Registered Storage Tank Sites	Subject Property and Adjoining Properties	0	0
Emergency Response Notification System	Subject Property	0	0

*Denotes Subject Property

The following is a discussion of the database findings:

Subject and Adjoining Properties

A former tenant of the subject property and an adjoining property were listed as RCRA Small Quantity Generator sites. The adjoining Duwamish River was also listed as a National Priorities List (NPL) site. Further information regarding these listing is provided below.

National Priorities List

1. Site Name: Lower Duwamish Waterway
Address: River Kilometer 2.5 to 10.8
Seattle, WA
Facility ID No.: WA0002329803
Distance: 50 feet
Direction: Northwest
Gradient: Downgradient
Type of Operation: Waterway
Potential for Impact: Low due to the fact that shallow groundwater on the subject property discharges to the adjoining Duwamish River

Discussion

Sediments in the lower Duwamish River are contaminated with semivolatile organic compounds, PCBs, inorganics, and organotins. In order to address the long-term threat to the human food chain and sensitive environments in the river, the EPA is adding this site to the NPL. The Duwamish River originates at the confluence of the Green and Black Rivers near Tukwila, Washington, then flows northeast for approximately 21 river kilometers, dividing at the southern end of Harbor Island to form the East and West waterways prior to discharging into Elliot Bay at Seattle, Washington. A segment of the river is maintained by the US Army Corps of Engineers as a federal navigation channel (i.e., the reach downchannel of Turning Basin #3).

The shorelines along the majority of the Duwamish Waterway have been developed for industrial and commercial operations. Much of the upland areas are heavily industrialized. In addition, this reach of the river is the receiving water body for discharges from over 100 storm drains, combined sewer overflows (CSOs), and other outfalls. Historical or current commercial and industrial operations include cargo handling and storage; marine construction; boat manufacturing; marina operations; paper and metals fabrication; food processing; and airplane parts manufacturing. Contaminants may have entered the river via several transport mechanisms, including spillage during product shipping and handling, direct disposal or discharge, contaminated ground water discharge, surface water runoff, storm water discharge, or contaminated soil erosion.

The presence of polychlorinated terphenyl (PCT), polychlorinated biphenyl (PCB), inorganic, semivolatile organic compound, and organotin contamination to surface sediments has been documented in the lower Duwamish River. In addition, subsurface sample results indicate that semivolatile organic compound, inorganic, and organotin contamination exists up to a depth of 1.2 meters (i.e., 4 feet) at some locations within the river. Numerous investigations performed by USEPA, the Boeing Company, King County Department of Natural Resources, and the National Oceanographic and Atmospheric Administration (NOAA) have been conducted with varying scopes and have led to the documentation of the contamination in the lower Duwamish River.

The lower Duwamish River is fished for recreational, commercial, and subsistence purposes. Three salmon hatcheries within the Green-Duwamish River system release approximately 10 million juvenile salmon each year. The Duwamish River is part of the traditional fishing grounds for the Muckleshoot and Suquamish Indian tribes. The National Marine Fisheries Service, has conducted numerous studies on the effects of contaminated sediments on biotic resources in the Duwamish River and elsewhere in Puget Sound. This research has shown that juvenile salmon from the Duwamish River exhibit reduced growth and immune system function relative to salmon from uncontaminated areas.

The lower Duwamish River serves as a migratory route, nursery, and osmoregulatory transition zone for several species of Pacific salmon. Puget Sound Chinook salmon are federally listed as threatened and utilize the lower Duwamish River during a critical stage of their migration from a fresh water to a salt water environment. The federal candidate species Coho salmon also occurs in this area as does a nesting territory for the federal listed threatened Bald eagle and a wetland.

Status (September 2001): EPA is considering various alternatives for this site.

State Hazardous Waste Sites

EDR's search of Washington's Confirmed & Suspected Contaminated Sites List (CSCSL) revealed thirteen CSCSL sites located within a one-mile radius of the subject property. Based on a review of available information presented in the environmental database report, the thirteen listed CSCSL sites are not expected to have adversely impacted the environmental condition of the subject property due to one or a combination of the following reasons: the sites are located lateral or downgradient of the subject property based on the topographical or hydraulic gradient; the sites are located greater than one-quarter mile relative to the subject property; and/or the sites are located hydraulically separated from the subject property by the Duwamish River. Therefore, based on the above reasons, the thirteen CSCSL sites are not expected to have adversely impacted the environmental condition of the subject property. Specific information about each CSCSL site is listed in the database in Appendix F.

RCRA Corrective Action TSD Facilities

There were two RCRA Corrective Action TSD (CORRACTS) Facilities located within a one-mile radius of the subject property. However, based on a review of available information presented in the environmental database report, the two listed CORRACTS facilities are not expected to have adversely impacted the environmental condition of the subject property due to the fact that the two sites are hydraulically separated from the subject property by the Duwamish River. Therefore, based on the above information, the two CORRACTS sites are not expected to have adversely impacted the environmental condition of the subject property. Specific information about each CORRACTS site is listed in the database in Appendix F.

Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS)

There was one CERCLIS site listed in the EDR database report. This site, identified as the Lower Duwamish Waterway, is previously discussed under the NPL section above.

CERCLIS No Further Remedial Action Planned (NFRAP) Sites

There was one CERCLIS NFRAP site listed in the EDR database report. However, based on a review of available information presented in the environmental database report, the one NFRAP site is not expected to have adversely impacted the environmental condition of the subject property due to the fact that the site is hydraulically separated from the subject property by the Duwamish River. Therefore, based on the above information, the one NFRAP site is not expected to have adversely impacted the environmental condition of the subject property. Specific information about the one NFRAP site is listed in the database in Appendix F.

Leaking Registered Storage Tanks (LRST)

There were six LRST sites listed in the environmental database. However, based on a review of available information presented in the environmental database report, the six LRST sites are not expected to have adversely impacted the environmental condition of the subject property due to the fact that the site is hydraulically separated from the subject property by the Duwamish River. Therefore, based on the above information, the six LRST sites are not expected to have adversely impacted the environmental condition of the subject property. Specific information about the six LRST sites is listed in the database in Appendix F.

Washington Voluntary Cleanup Program Sites/Washington Independent Cleanup Report Sites

The Independent Cleanup Reports (ICR) are remedial action reports issued to the Washington Department of Ecology by the owner or operator of the site. The remedial actions have been conducted without department oversight or approval and are not under an order or decree. EDR's search of Washington's ICR Sites revealed a total of five ICR sites located within a one-half-mile radius of the subject property. In addition, two Voluntary Cleanup Program (VCP) sites were listed in the database report.

Based on a review of available information presented in the environmental database report, the listed ICR and Voluntary Cleanup Program sites are not expected to have adversely impacted the environmental condition of the subject property due to one or a combination of the following reasons: the site(s) are listed as "soil only" contamination, where subsurface soils are the only media determined to have been impacted; the sites are located lateral or downgradient of the subject property based on the topographical or hydraulic gradient; the sites are reported as having been successfully remediated; or the sites are located greater than one-eighth mile relative to the subject property. Therefore, based on the above reasons, the seven ICR and VCP sites are not expected to have adversely impacted the environmental condition of the subject property. Specific information

about each ICR and VCP site is listed in the database in Appendix F.

Resource Conservation and Recovery Act Small Quantity Generators

The Small Quantity Generator Sites are:

1. Site Name: XTRA Lease Seattle Branch
 Address: 10180 W. Marginal Place South
 Seattle, WA
 Facility ID No.: WA0000016220
 Distance: Subject Property
 Direction: Subject Property
 Gradient: Subject Property
 Reported Waste Codes: Not Reported
 Violations: No Violations
 Notes: This tenant was not identified on the subject property. No
 further action regarding this listing is recommended at this
 time.

2. Site Name: USPS Seattle P&DC
 Address: 10700 27th Avenue South
 Seattle, WA
 Facility ID No.: WAH000000596
 Distance: +/- 300 Feet
 Direction: Southeast
 Gradient: Lateral
 Reported Waste Codes: Not Reported
 Violations: No Violations

7.0 PROPERTY VISIT

Property Solutions visited the subject property on August 18, 2004. Mr. Richard G. Levis, Northwest Regional Manager conducted the property visit and was escorted by Mr. Craig Peterson, representative of Freemont Associates. Property Solutions did not encounter inaccessible areas during the property visit. Property Solutions is not aware of inaccessible areas. Weather conditions at the time of the property visit consisted of sunny skies with an approximate outside air temperature of 80 degrees Fahrenheit.

Photographs taken during the property visit are included in Appendix B.

7.1 ASTM Scope Considerations

7.1.1 Underground Storage Tanks

No evidence of underground storage tanks (USTs) was observed on the subject property during the property visit.

Based upon the above information, no further action is recommended.

No evidence of high pressure gas or liquid petroleum transportation pipelines was observed within ten feet of the structures on the subject property. Review of available property maps did not reveal the presence of easements for high pressure gas or liquid petroleum transportation pipelines within ten feet of the structures on the subject property.

7.1.2 Aboveground Storage Tanks

No active aboveground storage tanks (ASTs) were observed on the subject property during the property visit. One inactive and empty propane AST was observed on the subject property. The propane AST is not expected to have adversely impacted the environmental condition of the subject property.

Based upon the above information, no further action is recommended.

7.1.3 Polychlorinated Biphenyl-Containing Electrical Equipment

A visual review was conducted for the presence of electrical equipment that could contain polychlorinated biphenyls (PCBs), an environmentally regulated material used in dielectric fluid in some electrical equipment. Seattle City Light provides electrical service to the subject property.

No transformers, capacitors, or large switch gear equipment were observed on the subject property during the property visit. Utility-owned pole-mounted transformers were identified along adjoining streets.

Based upon the above information, no further action is recommended.

7.1.4 Hydraulic Equipment

No evidence of hydraulic equipment was observed on the subject property during the property visit.

Based upon the above information, no further action is recommended.

7.1.5 Chemical, Hazardous Materials, and Raw Materials Storage and Usage

Chemicals stored on the subject property are minimal quantities of domestic cleaning chemicals, maintenance chemicals and paints. In addition, one 55-gallon drum containing anti-freeze, one 55-gallon drum containing new oil, and one 35-gallon drum containing grease was observed within one of the steel buildings. An additional four 55-gallon drums containing grease and concrete finishers were observed on the exterior portion of the subject property. These drums are the responsibility of Freemont Associates. No staining or leaking was observed below the drums. As a best management practice, Property Solutions recommends that the drums be placed under cover and on a concrete slab to prevent direct exposure to stormwater and surficial soils. Based on observations made during the property visit, the observed chemicals are not expected to be an environmental concern to the subject property at this time.

Containers found on the subject property during the property visit were observed to have no leaks or spills, and appeared to be properly stored. The chemicals observed at the subject property during the property visit are not expected to have adversely impacted the environmental condition of the subject property.

7.1.6 Waste Generation, Storage, and Disposal

Solid waste generated at the subject property consisted of domestic municipal waste and recyclable materials. Solid waste at the subject property is stored in separate trash containers located on the subject property. Municipal solid waste generated at the subject property is removed by a private waste hauler. Sanitary waste generated at the subject property is discharged to the Val-Vue sanitary sewerage system.

No evidence of hazardous waste generation, storage, or disposal was observed during the property visit.

Based upon the above information, no further action is recommended.

7.1.7 Wells, Sumps, Pits, and Floor Drains

No wells, sumps, pits, or floor drains were observed on the property during the property visit.

Based upon the above information, no further action is recommended.

7.1.8 Stormwater Runoff and Surface Water

The subject property is partially improved with the footprints of the subject buildings. The remainder of the subject property consists of limited landscaped areas and gravel parking areas. Stormwater runoff is expected to exit the subject property via overland flow and enter a limited number of stormwater collection inlets located on the subject property and discharge to the municipal stormwater collection system. Stormwater is also expected to percolate through the gravel parking areas.

The 1972 Amendments to the Federal Water Pollution Control Act (commonly known as the Clean Water Act [CWA]) prohibit the discharge of any pollutant to waters of the United States from a point source unless the discharge is authorized by a National Pollutant Discharge Elimination System (NPDES) permit. In 1987, the CWA was again amended by Congress to require implementation of a comprehensive national program for addressing problematic non-agricultural, non-point sources of stormwater discharge. The rules and regulations of the NPDES program are included in 40 CFR 122.26.

Stormwater permitting for a property is based on the property's Standard Industrial Classification (SIC) Code (category of industrial activity). However, the NPDES program includes a "no exposure" exemption for facilities within an applicable category of industrial activity. Based on 40 CFR 122.26 B(14), the subject property must obtain an NPDES Stormwater Discharge Permit only if material handling equipment or activities, raw materials, intermediate products, final products, waste materials, by-products, or industrial machinery is exposed to stormwater. As materials and activities described above are not associated with the subject property, stormwater permitting is not expected to be applicable at this time.

No surface water bodies (i.e., springs or swamps) were observed on the subject property.

Based upon the above information, stormwater runoff and surface water are not expected to be environmental concerns at this time. No further action is recommended at this time.

7.1.9 Lagoons, Septic Systems, and Separators

No evidence of lagoons, septic systems, or separators was observed on the subject property during the property visit.

Property Solutions is currently awaiting final responses from the Val-Vue sewer district and the King County Environmental Health Department regarding the historical presence of septic systems on the subject property and verification of the property's current connection to the municipal sanitary sewerage system. According to Mr. Scheuman, the subject property utilizes a private sanitary sewerage system that is pumped to the Val-Vue sanitary sewerage system.

Based upon the above information, no further action is recommended.

7.1.10 Stressed Vegetation, Staining, and Odors

No evidence of stressed vegetation, staining, or odors was noted on the subject property during the property visit, with the exception of one surficial stain noted on the Dick's Towing lot. The stain measured approximately 2' x 2', was surficial in nature, and was observed on a gravel floor within a covered storage building.

Based upon the limited extent of the stain, this stain is not expected to have significantly adversely impacted the environmental condition of the subject property. However, as a best management

practice, the stained gravel should be removed and disposed of in accordance with applicable regulations.

7.1.11 Surficial Disturbance

No evidence of surficial disturbances was observed on the subject property during the property visit.

Based upon the above information, no further action is recommended.

7.1.12 On-Property Dry Cleaners

No dry cleaning operations were observed at the subject property at the time of the property visit.

No dry cleaners were identified during the historical review of the subject property.

7.2 ASTM Non-Scope Considerations

7.2.1 Asbestos-Containing Materials

During the course of the property visit, Property Solutions performed a preliminary review of interior, accessible areas of the subject buildings for the presence of suspect asbestos-containing materials (ACMs). This limited review was conducted for overview purposes only; additional suspect materials may exist in concealed locations (behind walls and ceilings, within machinery, etc.). Also, not all suspect materials may have been sampled due to the condition or the location of the suspect materials. Destructive sampling of suspect ACMs was not performed. Suspect ACMs in an overall undamaged condition were not sampled, as that will damage the materials. Property Solutions will not be responsible for damaging materials or causing the materials to become friable. The USEPA defines asbestos-containing material as material containing greater than one percent asbestos. This review was not a pre-demolition/renovation survey or for regulatory submittal purposes.

Based on the date of construction (1987), review of available building information, and observations made during the property visit, ACMs are not expected to have been used during construction of the subject buildings.

Based upon the above information, no further action is recommended at this time.

7.2.2 Radon

The subject property is located in Zone 3 per the USEPA's Map of Radon Zones. According to the EDR Database Report, 106 canisters were placed at locations throughout King County. The mean value was 0.334 picoCuries per Liter (pCi/L) for first floor living areas and 0.538 pCi/L for basement living areas. The USEPA action level is 4.0 pCi/L.

Based on the above information and the non-residential use of the subject building, radon is not expected to be an environmental concern at this time.

7.2.3 Lead-Based Paint

Based on the various reported dates of construction of the subject building (1987), it is unlikely that lead-based paints were used during building construction. Painted surfaces within the subject buildings were generally observed to be in an undamaged condition.

Based on the commercial/industrial use of the subject buildings and construction date, LBP is not expected to be an environmental concern. No further action is recommended at this time.

7.2.4 Lead in Drinking Water

Drinking water for the subject property is provided by the City of Tukwila. The water provider was required to perform system-wide lead screening of their water system starting in 1992, under the USEPA "Lead and Copper Regulations" (Federal Register Volume 56, No. 26460). These regulations, promulgated in June 1991, require public water systems to perform screening and provide for public notification and corrective action to reduce the lead hazards present in the water system.

Review of the City of Tukwila's Drinking Water Quality Annual Report revealed that City of Tukwila's public water supply has met the 90th percentile for the lead action level of 15 parts per billion (ppb), and is currently in compliance with the USEPA's Lead and Copper Regulations.

7.2.5 Potential Wetlands

No evidence of wetland areas was observed on the subject property during the property visit. However, review of the United States Department of the Interior, National Wetland Inventory map of Seattle South, Washington revealed that delineated wetlands were previously located on the subject property. The wetlands area was identified as "Freshwater Emergent Wetlands (PEMC)" and measured approximately 4.05-acres.

As the subject property is currently improved with gravel surface parking lots and no evidence of wetlands was observed on the subject property at the time of the property visit, no further action is recommended at this time.

Based upon the above information, wetland areas are not expected to be an environmental concern at this time. No further action is recommended.

A copy of the wetland map is included in Appendix A.

7.2.6 Air Emissions

No major air emissions sources were identified at the subject property during the property visit.

Based upon the above information, no further action is recommended.

7.2.7 Mold/ Water Intrusion

Molds produce tiny spores to reproduce, which waft through the indoor and outdoor air continually. When mold spores land on a damp spot indoors, they may begin growing and digesting whatever they are growing on in order to survive. There are molds that can grow on wood, paper, carpet, and foods. When excessive moisture or water accumulates indoors, mold growth will often occur, particularly if the moisture problem remains undiscovered or un-addressed. There is no practical way to eliminate all molds and mold spores in the indoor environment; the way to control indoor mold growth is to control moisture. In addition, mold growth may be a problem after flooding.

No obvious visual evidence of mold, water intrusion, water damage, or standing water was observed in the interior portions of the subject building accessed by Property Solutions during the property visit. No musty odors indicative of a moisture problem or porous materials such as carpets and insulation in damp niches were observed during the property visit. No botanical materials such as bark chips or potted plants in moist locations such as an atrium were observed during the property visit. No indoor water features such as fountains, indoor waterfalls, or indoor swimming pools were observed in the subject building. No problems evident in the building envelope or problematic conditions surrounding the air intake were observed. No operatives conducive to bioaerosol generation such as animal confinement operations, agricultural activities, or wetlands were observed on the subject property or adjacent properties. This limited visual review was conducted for overview purposes only; mold may exist in concealed locations (behind walls, wallpaper, and ceilings, etc.).

8.0 CONCLUSIONS AND RECOMMENDATIONS

We have performed a Phase I Environmental Assessment in conformance with the scope and limitations of ASTM Practice E1527-00 of the Desimone/Oxbow Freemont property located at 2600 South 102nd Street and 10110 - 10180 West Marginal Place, Tukwila, King County, Washington 98168. Any exceptions to, or deletions from, this practice are described in Section 1.0 of this report.

This assessment has revealed no evidence of recognized environmental conditions in connection with the subject property except for the following:

1. Chemicals stored on the subject property are minimal quantities of domestic cleaning chemicals, maintenance chemicals and paints. An additional four 55-gallon drums containing grease and concrete finishers were observed on the exterior portion of the subject property. These drums are the responsibility of Freemont Associates. No staining or leaking was observed below the drums. Based on observations made during the property visit, the

observed chemicals are not expected to be an environmental concern to the subject property at this time.

As a best management practice, Property Solutions recommends that the drums be placed under cover and on a concrete slab to prevent direct exposure to stormwater and surficial soils.

2. No evidence of stressed vegetation, staining, or odors was noted on the subject property during the property visit, with the exception of one surficial stain noted on the Dick's Towing lot. The stain measured approximately 2' x 2', was surficial in nature, and was observed on a gravel floor within a covered storage building.

Based upon the limited extent of the stain, this stain is not expected to have significantly adversely impacted the environmental condition of the subject property. However, as a best management practice, the stained gravel should be removed and disposed of in accordance with applicable regulations.

9.0 REFERENCES

9.1 Information Sources

1. United States Geological Survey's 7.5-minute topographic quadrangle map of Seattle South, Washington.
2. United States Department of Agriculture, Soil Conservation Services' Soil Survey of King County, Washington.
3. Geologic Map of Washington (1961), compiled by A.E. Weissenborn
4. United States Department of the Interior, National Wetland Inventory Map for Seattle South, Washington.

9.2 Definitions

Adjoining properties -- any real property or properties the border of which is contiguous or partially contiguous with that of the property, or that would be contiguous or partially contiguous with that of the property but for a street, road, or other public thoroughfare separating them.

Appropriate inquiry -- that inquiry constitution "all appropriate inquiry into the previous ownership and uses of the property consistent with good commercial or customary practice" as defined in CERCLA, 42 USC§9601(35)(B), that will give a party to a *commercial real estate* transaction the *innocent landowner defense* to CERCLA liability (42 USC§9601(A) and (B) and §9607(b)(3)), assuming compliance with other elements of the defense.

Data failure – a standard historical source may be excluded (1) if the source is not reasonably ascertainable, or (2) if past experience indicates that the source is not likely to be sufficiently useful, accurate, or complete in terms of satisfying 7.3.2 (uses of the property).

Historical recognized environmental condition – environmental condition which in the past would have been considered a recognized environmental condition, but which may or may not be considered a recognized environmental condition currently. The final decision rests with the environmental professional and will be influenced by the current impact of the historical recognized environmental condition on the property. If a past release of any hazardous substances or petroleum products has occurred in connection with the property and has been remediated, with such remediation accepted by the responsible regulatory agency (for example, as evidenced by the issuance of a no further action letter or equivalent), this condition shall be considered an historical recognized environmental condition and included in the findings section of the Phase I Environmental Assessment report. The environmental professional shall provide an opinion of the current impact on the property of this historical recognized environmental condition in the opinion section of the report. If this historical recognized environmental condition is determined to be a recognized environmental condition at the time of the Phase I Environmental Assessment is conducted, the condition shall be identified as such and listed in the conclusions section of the report.

Material threat – a physically observable or obvious threat which is reasonably likely to lead to a release that, in the opinion of the environmental professional, is threatening and might result in impact to public health or the environment. An example might include an aboveground storage tank that contains a hazardous substance and which shows evidence of damage. The damage would represent a material threat if it is deemed serious enough that it may cause or contribute to tank integrity failure with a release of contents to the environment.

Practically reviewable – information that is practically reviewable means that the information if provided by the source in a manner and in a form that, upon examination yields information relevant to the property without the need for extraordinary analysis of irrelevant data. The form of the information shall be such that the user can review the records for a limited geographic area. Records that cannot be feasibly retrieved by reference to the location of the property or a geographic area in which the property is located are not generally practically reviewable.

Publicly available – information that is publicly available means that the source of the information allows access to the information by anyone upon request.

Reasonably Ascertainable/ Standard Sources – availability of record information varies from information source to information source, including governmental jurisdictions. The user or environmental professional is not obligated to identify, obtain, or review every possible record that might exist with respect to a property. Instead, this practice identifies record information that shall be reviewed from standard sources, and the user or environmental professional is required to review only record information that is reasonably ascertainable to those standard sources. Record information that is reasonably ascertainable means (1) information that is publicly available, (2) information that is obtainable from its source within reasonable time and cost constraints, and (3)

information that is practically reviewable.

Reasonable time and cost – information that is obtainable within reasonable time and cost constraints means that the information will be provided by the source within 20 calendar days of receiving a written, telephone, or in-person request at no more than an nominal cost intended to cover the source's cost of retrieving and duplicating the information. Information that can only be reviewed by a visit to the source is reasonably ascertainable if the visit is permitted by the source within 20 days of request.

Recognized environmental conditions – the presence or likely presence of any hazardous substances or petroleum products on a property under conditions that indicate an existing release, a past release, or a material threat of a release of any hazardous substances or petroleum products into structures on the property or into the ground, ground water, or surface water of the property. The term includes hazardous substances or petroleum products even under conditions in compliance with laws. The term is not intended to include de minimis conditions that generally do not present a material risk of harm to public health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. Conditions determined to be de minimis are not recognized environmental conditions.

User – the party seeking to use Practices E 1527 or E 1528 to perform an environmental assessment of the property. A user may include, without limitation, a purchaser of property, a potential tenant of property, an owner of property, a lender, or a property manager.

9.3 Acronyms

ACM – asbestos-containing material

AST – aboveground storage tank

ASTM – American Society for Testing and Materials

bgs – below ground surface

CERCLA – Comprehensive Environmental Response, Compensation and Liability Act of 1980
(as amended, 42 USC § 9601 et seq.)

CERCLIS – Comprehensive Environmental Response, Compensation and Liability Information
System (maintained by EPA)

CFR – Code of Federal Regulations

CORRACTS – facilities subject to Corrective Action under RCRA

EA – environmental assessment

ECRA – Environmental Cleanup Responsibility Act

EDR – Environmental Data Resources, Inc.

EPCRA – Emergency Planning and Community Right to Know Act ((also known as SARA Title
III), 42 USC § 11001 et seq.)

ERNS – Emergency Response Notification System

FOIA – United States Freedom of Information Act (5 USC § 552 et seq.)


HREC – historical recognized environmental condition

ISRA – Industrial Site Recovery Act

LBP – lead-based paint
LRST – leaking registered storage tank
LUST – leaking underground storage tank
MSDS – material safety data sheet
NCP – National Contingency Plan
NFRAP – former CERCLIS sites where no further remedial action is planned under CERCLA
NPDES – national pollutant discharge elimination system
NPL – National Priorities List
NVLAP – National Voluntary Laboratory Accreditation Program
OSHA – Occupational Safety and Health Administration
PACM – presumed asbestos-containing material
PCBs – polychlorinated biphenyls
PLM – polarized light microscopy
PRP – potentially responsible party (pursuant to CERCLA 42 USC § 9607(a))
RCRA – Resource Conservation and Recovery Act (as amended, 42 USC § 6901 et seq.)
RCRIS – Resource Conservation and Recovery Act Information System
REC – recognized environmental condition
ROC – record of communication
RST – registered storage tank
SACM – suspect asbestos-containing material
SARA – Superfund Amendments and Reauthorization Act of 1986 (amendment to CERCLA)
SIC – Standard Industrial Classification
TEM – transmission electron microscopy
TSDF – hazardous waste treatment, storage or disposal facility
USC – United States Code
USEPA – United States Environmental Protection Agency
USGS – United States Geological Survey
UST – underground storage tank

APPENDIX A

MAPS



US DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY 7.5" TOPOGRAPHIC QUADRANGLE



Property Solutions Inc.

Desimone/Oxbow Freemont
2600 South 102nd Street and 10110 -
10180 West Marginal Place
Tukwila, Washington 98168



Project No.: 20042586



Topo Quad Name: Seattle South, WA

Property Boundaries are Approximate

DFT 001663



AREA EXHIBIT SKETCH

WEST MARGINAL PLACE

DFT 001664

APPENDIX B

PROPERTY PHOTOGRAPHS

PHOTO 1. View of subject buildings



PHOTO 2. View of temporary office




Property Solutions Inc.
Project No.: 20042586

DFT 001666

PHOTO 3. View of temporary office



PHOTO 4. View of container repair area



Property Solutions Inc.
Project No.: 20042586

DFT 001667

PHOTO 5. View of temporary office





PHOTO 6. View of storage shed



Property Solutions Inc.
Project No.: 20042586

DFT 001668

PHOTO 7. View of subject property




PHOTO 8. View of subject property



Property Solutions Inc.
Project No.: 20042586

DFT 001669

PHOTO 9. View of subject property




PHOTO 10. Interior view of subject building



Property Solutions Inc.
Project No.: 20042586

DFT 001670

PHOTO 11. Interior view of subject building





PHOTO 12. Interior view of subject building



Property Solutions Inc.
Project No.: 20042586

DFT 001671

PHOTO 13. North adjoining property




PHOTO 14. Empty AST




Property Solutions Inc.
Project No.: 20042586

DFT 001672

PHOTO 15. Chemical storage area



PHOTO 16. Chemical storage area



Property Solutions Inc.
Project No.: 20042586

DFT 001673

PHOTO 17. Chemical storage area



Property Solutions Inc.
Project No.: 20042586

DFT 001674

APPENDIX C

CITY DIRECTORIES



EDR™ Environmental
Data Resources Inc

The EDR-City Directory
Abstract

**Pacific NW Transfer
2600 South 102nd Street
Seattle, WA 98168**

August 25, 2004

Inquiry Number: 1254746-4

**The Standard
In Environmental
Risk Management
Information**

**440 Wheelers Farms Road
Milford, Connecticut 06460**

Nationwide Customer Service

**Telephone: 1-800-352-0050
Fax: 1-800-231-6802**

DFT 001676

Disclaimer - Copyright and Trademark Notice

This report contains information obtained from a variety of public and other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL EDR BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES.** It can not be concluded from this report that coverage information for the target and surrounding properties does not exist from other sources. Any analyses, estimates, ratings or risk codes provided in this report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Any liability on the part of EDR is strictly limited to a refund of the amount paid for this report.

Copyright 2004 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

APPENDIX D

AERIAL PHOTOGRAPHS

APPENDIX E

FIRE INSURANCE MAPS

This report contains information obtained from a variety of public and other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL EDR BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. It can not be concluded from this report that coverage information for the target and surrounding properties does not exist from other sources. Any analyses, estimates, ratings or risk codes provided in this report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Any liability on the part of EDR is strictly limited to a refund of the amount for this report.

Copyright 2004 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates, is prohibited without prior written permission. EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

DFT 001687

APPENDIX F

CORRESPONDENCE

08/11/04 WED 11:08 FAX 206 664 8842
FROM : CONSTRUCTORS-PACIFIC

MELLON - SEATTLE ADMIN
PHONE NO. : 206 632 6609

001
Aug. 11 2004 12:21PM P1

FAX 206-664-8827
503 528 1333

To: Kim
Fm: Charlene

Re: Desimone Property at West Marginal Place and 102nd

Here are the tenants and addresses:

10110 West Marginal Place S.	Sefnco - leaving, if not gone??
10140 West Marginal Place S.	Dicks Towing (office building)
10160 West Marginal Place S.	Royal Wolfe Transfer (office building)
a	Certified Cleaning
b	Pacific Freight
10180 West Marginal Place S.	Eagle Systems (office building)
a	vacant
✓ 2600 S. 102 nd	Pacific NW Transfer (office building)
a	SMC
b	Sullivan (shop buildings)
c	vacant

We also store a small amount of equipment on the 102nd piece of property.

DFT 001689



U.S. Environmental Protection Agency Envirofacts Data Warehouse

[Recent Additions](#) | [Contact Us](#) | [Print Version](#) EF Search:

GO

[EPA Home](#) > [Envirofacts](#) > [Multisystem](#) > [Query Results](#)


Envirofacts

Query Results

 Report
an
Error

ZIP Code: 98168

LIST OF EPA-REGULATED FACILITIES IN ENVIROFACTS

To see a report on a facility click on the underlined Facility Name. Click on the underlined "View Facility Information" link to view EPA Facility information for the facility.

[Go To Bottom Of The Page](#)

<u>FACILITY NAME/ADDRESS</u>	<u>FACILITY INFORMATION</u>	<u>Permitted Discharges to Water?</u>	<u>Toxic Releases Reported?</u>	<u>Hazardous Waste Handler?</u>	<u>Active or Archived Superfund Report?</u>	<u>Air Releases Reported?</u>
144TH MACADAM S 144TH ST & MACADAM RD S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
2ND AVE DRUG LAB SEATTLE 12836 2ND AVE S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
7 ELEVEN FOOD STORE 13456 1ST AVE S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
ABOUT TIME AUTO REBUILD 1045 S 136TH ST SEATTLE, WA 981682759	View Facility Information	NO	NO	YES	NO	NO
AIRPORT WAY DRUM AIRPORT WAY S & BOEING ACCESS SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
AIRTOUCH MALL RATS 16400 SOUTHCENTER PKWY SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
AIRTRON INC 4479 S 134TH PL TUKWILA, WA 981686204	View Facility Information	NO	NO	YES	NO	NO

DFT 001690

ALASKA AIR FORWARDING INC 4443 S 134TH PL TUKWILA, WA 981686204	View Facility Information	NO	NO	YES	NO	NO
AMERICAN MEDICAL RESPONSE 13075 GATEWAY DR STE 100 SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
ATACS PRODUCTS INC INTERURBAN AVE 14040 INTERURBAN AVE S TUKWILA, WA 981684723	View Facility Information	NO	NO	YES	NO	NO
AUTO SITE AUTOMOTIVE 11803 DES MOINES MEMORIAL DR SEATTLE, WA 981681242	View Facility Information	NO	NO	YES	NO	NO
AUTOPAINT & IND SUPPLY INC 13437 1ST AVE S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
BBC DODGE INC 1ST AVE 14650 1ST AVE S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
BECKER TRUCKING INC 12677 E MARGINAL WAY S SEATTLE, WA 981682562	View Facility Information	NO	NO	YES	NO	NO
BERENDSEN FLUID POWER 134TH PL 4550 S 134TH PL STE 104 SEATTLE, WA 981683238	View Facility Information	NO	NO	YES	NO	NO
BERKLEY ENGINEERING CONST S 124TH ST & HWY 99 SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
BERNARD IMPORTS INC 11020 E MARGINAL WAY S TUKWILA, WA 981681935	View Facility Information	NO	NO	YES	NO	NO
BERNARD IMPORTS INC TUKWILA						

DFT 001691

14100 INTERURBAN AVE S TUKWILA, WA 981684614	View Facility Information	NO	NO	YES	NO	NO
BERT WELL INDUSTRIES INCORPORATED 6411 S. 143RD ST. TUKWILA, WA 98168	View Facility Information	NO	YES	NO	NO	NO
BOB FOXS BURIEN MAZDA 13803 1ST AVE S BURIEN, WA 981683413	View Facility Information	NO	NO	YES	NO	NO
BOEING DUWAMISH OFFICE PARK 2925 S 112TH TUKWILA, WA 98168	View Facility Information	NO	NO	YES	NO	NO
BOEING MILITARY FLIGHT CENTER 10002 E MARGINAL WAY S SEATTLE, WA 98168- 1802	View Facility Information	YES	NO	NO	NO	NO
BOEING SPARES DISTRIBUTION CENTER 2001 S 146TH S SEATAC, WA 98168-0	View Facility Information	YES	NO	NO	NO	NO
BOEING SPARES DISTRIBUTION CENTER SEATAC 2201 S 142ND ST SEATAC, WA 98168	View Facility Information	NO	NO	YES	NO	NO
BOWERS MACHINE CO 13032 INTERURBAN AVE S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
BP ABANDONED CONTAINER 10 FT W OF 13310 INTERURBAN AV TUKWILA, WA 98168	View Facility Information	NO	NO	YES	NO	NO
BP SERVICE STATION 03153 14807 1ST AVENUE SOUTH SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
BP SERVICE STATION 03154 14415 SOUTH PACIFIC HIGHWAY SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
CARRIER CORP BLDG SYSTEMS SVCS						

DFT 001692

3215 116TH ST STE 133 TUKWILA, WA 98168	View Facility Information	NO	NO	YES	NO	NO
CASCADE VISTA DRUMS 13823 1ST AVE S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
CHEVRON STA 6009 3099 10805 E MARGINAL WAY TUKWILA, WA 981681931	View Facility Information	NO	NO	YES	NO	NO
CIRCLE K STORE 1476 12660 1ST AVENUE SOUTH SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
CLIFF HOUSERS AUTOMOTIVE 806 S 112TH ST SEATTLE, WA 981682144	View Facility Information	NO	NO	YES	NO	NO
CUSTOM GEAR INC 10834 E MARGINAL WAY S SEATTLE, WA 98168- 1932	View Facility Information	YES	NO	NO	NO	NO
DOUGLAS PRINTING LTD 14818 PACIFIC HWY S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
DS PURCELL PAINTING INC 144TH 6456 S 144TH ST TUKWILA, WA 98168	View Facility Information	NO	NO	YES	NO	NO
EARLS MACHINE SHOP 13625 1ST AVE S BURIEN, WA 981683403	View Facility Information	NO	NO	YES	NO	NO
ECKER TRUCKING INCORPORATED TUKWILA 6350 SOUTH 143RD STREET TUKWILA, WA 98168	View Facility Information	YES	NO	YES	NO	NO
EDGMON& SON TRUCKING 12677 E MARGINAL WAY S EDGMON& SON SEATTLE, WA 98168	View Facility Information	YES	NO	NO	NO	NO
EMERY WORLDWIDE 14221 20TH AVE S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO

DFT 001693

ENGSTROM MACHINE WORKS INC 6400 S 143RD PL TUKWILA, WA 981684606	View Facility Information	YES	NO	YES	NO	NO
FARWEST PAINT MANUFACTURING COMPANY 4522 S. 133RD ST. TUKWILA, WA 98168	View Facility Information	YES	YES	YES	NO	NO
FOSTORIA PARK INDUSTRIAL CENTER 4400 BLK S 133RD & S 134TH ST TUKWILA, WA 981683280	View Facility Information	NO	NO	YES	NO	NO
FRED MEYER SEATTLE 14300 1ST AVENUE SOUTH SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
GATEWAY NORTH 3415 S 116TH ST BLDG 5 SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
GENES ENGINE HAUS 13847 MILITARY RD S SEATTLE, WA 981683940	View Facility Information	NO	NO	YES	NO	NO
GEORGE HEISER BODY CO INC TUKWILA 11210 TUKWILA INTERNATIONAL BL TUKWILA, WA 98168	View Facility Information	NO	NO	YES	NO	NO
GEORGE HEISER BODY INC 11210 TUKWILA INT'L BLVD TUKWILA, WA 98168	View Facility Information	NO	NO	NO	NO	YES
GLEN GRANT CHEVROLET INC 14400 1ST AVE S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
GOODYEAR TIRE & RUBBER 12115 E MARGINAL WAY S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
GRAND EAGLE SERVICES INCORPORATED 10831 EAST MARGINAL WAY SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
GROUP HEALTH						

DFT 001694

COOPERATIVE ROC TUKWILA 12400 E MARGINAL WAY S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
GT DEVELOPMENT CORP TUKWILA 6437 S 144TH ST TUKWILA, WA 98168	View Facility Information	NO	NO	YES	NO	NO
HIGHLINE HOSPITAL SPECIALTY CENTER 12844 MILITARY RD SW TUKWILA, WA 98168	View Facility Information	NO	NO	YES	NO	NO
HSD HIGHLINE BOULEVARD PARK WAREHOUSE 12833 20TH AVE S SEATTLE, WA 981682916	View Facility Information	NO	NO	YES	NO	NO
HUSKY INTERNATIONAL 13123 48TH AVENUE SOUTH SEATTLE, WA 98168	View Facility Information	NO	NO	NO	NO	YES
HUSKY TRUCK CENTER 11222 E MARGINAL WAY S S END O TUKWILA, WA 98168	View Facility Information	NO	NO	YES	NO	NO
I5 HWY 900 SPILL I5 MP 157 NORTHBOUND AT HWY 90 TUKWILA, WA 98168	View Facility Information	NO	NO	YES	NO	NO
IKON OFFICE SOLUTIONS 12606 INTERURBAN AVE S TUKWILA, WA 981683314	View Facility Information	NO	NO	YES	NO	NO
INCO EXPRESS INCORPORATED 3600 SOUTH 124TH STREET SEATTLE, WA 981682595	View Facility Information	NO	NO	YES	NO	NO
INGERSOLL RAND 11222 E MARGINAL WAY S N END O SEATTLE, WA 981681954	View Facility Information	NO	NO	YES	NO	NO
INTERURBAN DRUM 0188 INTERURBAN AVE S & S 143RD ST	View Facility Information	NO	NO	YES	NO	NO

DFT 001695

TUKWILA, WA 98168						
JL SERVICE OR ONE TEN AUTO REPAIR 11180 EAST MARGINAL WAY SOUTH SEATTLE, WA 981681943	View Facility Information	NO	NO	YES	NO	NO
JOHN H HARLAND CO SEATTLE 3325 S 116TH ST STE 161 SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
KAISER DEVELOPMENT CO 12855 48TH AVE S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
KING CNTY PARKS SUNSET SHOP 13659 18TH AVE S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
KING CNTY POLICE BURIE 14905 6TH AVE SW SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
KING CNTY ROAD DEPT BUR 13831 18TH AVE S BURIEN, WA 98168	View Facility Information	NO	NO	YES	NO	NO
KONICA BUSINESS MACHINES USA 14900 INTERURBAN AVE S SEATTLE, WA 981684684	View Facility Information	NO	NO	YES	NO	NO
LARRYS UNIQUE AUTOBODY REBUILD 14836 1ST AVE S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
LEES ONE HOUR DRYCLEAN 14450 34TH AVE S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
LOWER DUWAMISH WATERWAY RK 2.5 TO RK 10.8 SEATTLE, WA 98168	View Facility Information	NO	NO	NO	YES	NO
MAACO AUTO PAINTING BODYWORKS 13646 1ST AVE S SEATTLE, WA 981683403	View Facility Information	NO	NO	YES	NO	NO
MACADAM ABANDONED PAINT	View Facility					

DFT 001696

SE COR OF S 137TH & MACADAM RD TUKWILA, WA 98168	Information	NO	NO	YES	NO	NO
MACADAM ROAD PAINT 13405 43RD AVE S TUKWILA, WA 98168	View Facility Information	NO	NO	YES	NO	NO
MALINAK GRACE S 149TH & DES MOINES WAY S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
MEASUREMENT SYSTEMS INTERNATIONAL INC 14240 INTERURBAN AVE S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
MEASUREMENT SYSTEMS INTL 12622 INTERURBAN AVE S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
METRO KING CNTY DOT TRANSIT 12100 12200 E MARGINAL WAY S SEATTLE, WA 98168	View Facility Information	YES	NO	YES	NO	NO
METRO KING CNTY DOT TRANSIT DIV S FAC 11911 E MARGINAL WAY S SEATTLE, WA 98168	View Facility Information	YES	NO	YES	NO	NO
METROMEDIA FIBER NETWORK SERVICES 3433 120TH PLACE SOUTH TUKWILA, WA 98168	View Facility Information	NO	NO	YES	NO	NO
MIKES AUSSIE MACHINE SHOP 12441 DES MOINES MEMORIAL DR SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
MILLENNIUM FORD INC 14600 AMBAUM BLVD SW SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
NAPA AUTO PARTS TUKWILA 14013 PACIFIC HWY S TUKWILA, WA 98168	View Facility Information	NO	NO	YES	NO	NO
NORTH STAR TRANSPORT INC SEATT 12455 PACIFIC HWY S	View Facility Information	NO	NO	YES	NO	NO

DFT 001697

SEATTLE, WA 98168						
NORTHWEST AUTO WRECKING 10230 E MARGINAL WY S TUKWILA, WA 98168- 1898	View Facility Information	YES	NO	NO	NO	NO
NW TRANSPORT SERVICE INC SEA 12855 48TH AVE S SEATTLE, WA 981683301	View Facility Information	NO	NO	YES	NO	NO
ONYX ENVIRONMENTAL SERVICES LLC 6350 S 143RD ST TRANSFER FACIL TUKWILA, WA 98168	View Facility Information	NO	NO	YES	NO	NO
OVERNIGHT TRUCKING 11231 E MARGINAL WAY S TUKWILA, WA 98168	View Facility Information	YES	NO	YES	NO	NO
OVERNITE TRANSP CO 12855 48TH AVE S STE 450 TUKWILA, WA 981683338	View Facility Information	NO	NO	YES	NO	NO
PACO PUMPS 3215 S 116TH ST STE 109 SEATTLE, WA 981681973	View Facility Information	YES	NO	YES	NO	NO
PENSKE TRUCK LEASING CO LP TUKWILA 12840 48TH AVE S TUKWILA, WA 98168	View Facility Information	NO	NO	YES	NO	NO
PERFORMANCE AUTO 14025 A 1ST AVE S BURIEN, WA 981683415	View Facility Information	NO	NO	YES	NO	NO
QUAKER STATE MINIT LUBE INC 11 1ST AVE 13654 1ST AVE S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
QUICK PRECISION INC 108 S 108TH SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
R & J AUTOBODY INC 10832 MYERS WAY S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO

DFT 001698

RACON INC 12628 INTERURBAN AVE S SEATTLE, WA 981683383	View Facility Information	NO	NO	YES	NO	NO
RELIABLE AUTO MOTORS & USED PARTS 14032 INTERURBAN AV S TUKWILA, WA 98168	View Facility Information	NO	NO	YES	NO	NO
ROAD RUNNER FREIGHT SPILL WASTE AT BECKE 6350 S 143RD ST RR FREIGHT TUKWILA, WA 98168	View Facility Information	NO	NO	YES	NO	NO
ROSSOE INC SEATTLE S 144TH ST S 144TH ST & DES MOINES WAY SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
SAFCO ENVIRONMENTAL 2212 S 144TH SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
SEA TAC FORD 11000 PACIFIC HWY S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
SEATTLE CITY LIGHT DUWAMISH TR T23N R4E S4 SE1/4 WM SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
SEATTLE FREIGHT SERVICE SR 599 SR 599 & SR 99 N SIDE OF S BOU SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
SEATTLE PUBLIC UTILITIES BURIE PUMP STA 14602 8TH AVE S BURIE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
SEATTLE SERVICE CTR 2006 S 146TH ST SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
SEATTLE WHITE GMC 14000 INTERURBAN AVE S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
SHELL OIL CO DES MOINES 12666 DES MOINES WAY	View Facility Information	NO	NO	YES	NO	NO

DFT 001699

SEATTLE, WA 98168						
SHUTTLEPARK INC 15667 PACIFIC HWY S SEATA, WA 981680160	View Facility Information	NO	NO	YES	NO	NO
SIMVEST INC 6410 S 143RD ST SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
SIX ROBBLEES INC 11010 PACIFIC HWY S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
SOUTH CENTRAL SCHOOL DIST 406 FOSTER H 4242 S 144TH ST SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
SOUTHGATE FORD INC 14500 1ST AVE S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
SOUTHTOWNE AUTO REBUILD INC 14864 TUKWILA INTERNATIONAL BL TUKWILA, WA 981684329	View Facility Information	NO	NO	YES	NO	NO
SPIROS ALIAGAS 14638 PACIFIC HWY S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
STRUCTURAL INSTRUMENTATION INC 4611 S 134TH PL TUKWILA, WA 98168	View Facility Information	NO	NO	YES	NO	NO
SUBURBAN PROPANE INC 12642 INTERURBAN AVE S TUKWILA, WA 98168	View Facility Information	NO	NO	YES	NO	NO
SUDDEN PRINTING INC 11009 1ST AVE S SEATTLE, WA 981681401	View Facility Information	NO	NO	YES	NO	NO
SYSTEM SEVEN REPAIR INC 10831 TUKWILA INTERNATION BLVD SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
TEXACO STATION 632320281 13435 INTERURBAN AV S TUKWILA, WA 98168	View Facility Information	NO	NO	YES	NO	NO
TEXACO STATION						

DFT 001700

632320396 14848 1ST AVE S SEATTLE, WA 981683425	View Facility Information	NO	NO	YES	NO	NO
THE BOEING COMPANY, GATEWAY 12687 GATEWAY DR SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
TIRE DISTRIBUTION SYSTEMS 11011 PACIFIC HWY S SEATTLE, WA 981681941	View Facility Information	NO	NO	YES	NO	NO
TOP AUTO INC SEATTLE 1ST AVE S 14302 1ST AVE S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
TR EQUIPMENT SERVICES TUKWILA 4712 S 134TH ST TUKWILA, WA 981683239	View Facility Information	NO	NO	YES	NO	NO
TRIAD MACHINERY INCORPORATED 11210 PACIFIC HIGHWAY SOUTH TUKWILA, WA 98168	View Facility Information	NO	NO	YES	NO	NO
TRUGREEN LANDCARE 14420 DES MOINES MEMORIAL DR SEATAC, WA 981683721	View Facility Information	NO	NO	YES	NO	NO
TUKWILA CONTAINER NE COR S 114TH ST & 49TH AVE S TUKWILA, WA 98168	View Facility Information	NO	NO	YES	NO	NO
TUKWILA OIL WASTE N SIDE S 115TH ST TUKWILA, WA 98168	View Facility Information	NO	NO	YES	NO	NO
TUKWILA SCHOOL DIST 4628 S 144TH ST TUKWILA, WA 98168	View Facility Information	NO	NO	YES	NO	NO
TUKWILA TOLUENE 3800 BLOCK S 115TH S SIDE OF S TUKWILA, WA 98168	View Facility Information	NO	NO	YES	NO	NO
U HAUL CO OF BURIEN 13645 1ST AVE S SEATTLE, WA 981683403	View Facility Information	NO	NO	YES	NO	NO
UNITED MOTORS 13911 PACIFIC HWY S	View Facility Information	NO	NO	YES	NO	NO

DFT 001701

TUKWILA, WA 98168						
UNITED TECHNOLOGIES OTIS ELEVATOR 13035 GATEWAY DR STE 157 SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
UNOCAL SS NO 6248 11845 DES MOINES WAY SOUTH SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
US DOJ DEA KENT TRAINING 2450 S 142ND SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
USPS SEATTLE PROCESSING & DISTRIBUTING CTR 10700 27TH AVENUE SOUTH SEATTLE, WA 981681899	View Facility Information	NO	NO	YES	NO	NO
USWCOM SEATTLE CHERRY CO 14605 8TH AVE S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
WALKER ASSOC 12652 INTERURBAN AVE S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
WALTS RADIATOR & MUFFLER 1ST AVE S 14653 1ST AVE S SEATTLE, WA 981683423	View Facility Information	NO	NO	YES	NO	NO
WASHINGTON MECHANICAL CONTRACT 13800 PACIFIC HWY S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
WEST SEATTLE TRANSMISSION 2920 6TH AVE S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
WESTERN CASCADE TRUCK INC 6440 S 143RD ST TUKWILA, WA 98168	View Facility Information	NO	NO	YES	NO	NO
XTRA LEASE SEATTLE BRANCH 10180 W MARGINAL PL S SEATTLE, WA 98168	View Facility Information	NO	NO	YES	NO	NO
YELLOW FREIGHT SYSTEM INC	View Facility					

DFT 001702

SEATTLE 12855 48TH S SEATTLE, WA 98168	Information	NO	NO	YES	NO	NO
--	-----------------------------	----	----	-----	----	----

[Go To Top Of The Page](#)**Total Number of Facilities Displayed: 145**


[EPA Home](#) | [Privacy and Security Notice](#) | [Contact Us](#)

Last updated on Tuesday, October 26th, 2004
http://oaspub.epa.gov/enviro/fii_master.fii_retrieve

DFT 001703

APPENDIX G

ENVIRONMENTAL DATABASE



EDR™ Environmental
Data Resources Inc

The EDR Radius Map with GeoCheck®

**Pacific NW Transfer
2600 South 102nd Street
Seattle, WA 98168**

Inquiry Number: 1254746.2s

August 23, 2004

The Standard in Environmental Risk Management Information

**440 Wheelers Farms Road
Milford, Connecticut 06460**

Nationwide Customer Service

**Telephone: 1-800-352-0050
Fax: 1-800-231-6802
Internet: www.edrnet.com**

DFT 001705

Disclaimer - Copyright and Trademark Notice

This report contains information obtained from a variety of public and other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL EDR BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. It can not be concluded from this report that coverage information for the target and surrounding properties does not exist from other sources. Any analyses, estimates, ratings or risk codes provided in this report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Any liability on the part of EDR is strictly limited to a refund of the amount paid for this report.

Copyright 2004 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Disclaimer Provided by Real Property Scan, Inc.

The information contained in this report has predominantly been obtained from publicly available sources produced by entities other than Real Property Scan. While reasonable steps have been taken to insure the accuracy of this report, Real Property Scan does not guarantee the accuracy of this report. Any liability on the part of Real Property Scan is strictly limited to a refund of the amount paid. No claim is made for the actual existence of toxins at any site. This report does not constitute a legal opinion.

DFT 001794

APPENDIX H PROFESSIONAL QUALIFICATIONS

RICHARD G. LEVIS
REGIONAL MANAGER, NORTHWEST REGION

(b)(6)



(b)(6)



KEVIN J. BILLINGS, P.E.

SENIOR VICE PRESIDENT

(b)(6)



(b)(6)

